

Significant rot where post was in contact with the ground

Base of Vertical Post



Top of Horizontal Beam



Metal flashing from top of beam is in poor condition



Side of Vertical Post



Close up of Portal Member

Base of Vertical Post



Significant rot where post was in contact with the ground

Top of Vertical Posts



Significant rot where beam bolted into post

Rot at end of beam



End of Horizontal Beam