SCD Revision Log 10-1-2018

Std Dwg #	Sheet #	Revision Description
4100	1	Corrected base width dimension and bolt slot width on plate pedestal base detail (upper left).
		Added collar height dimension and adjusted overall height of transformer base.
4103	2	Note 4: Corrected reference to SCD 4105.
4110	1 and 2	Revised to specify flush welded end cap for bottom tube.
		Revise cable entry hole to 1.5" (View A-A).
		Revised clamp bolt length and clamp gap information (View A-A).
4120	1	Arm rise dimension: added Design 13 to the list of poles with a 3" to 30" range.
	2	Changed pole size column to show just the base diameter in Table 1 Part A. Pole height to be determined by designer.
	9	Note 16: Added requirement that a mechanical dampening device must be included on all arms 59' and greater.
4121	1	Mechanical dampening device callout: corrected reference to note 15.
		Updated MIS references for luminaire and bracket arm.
	2	Changed pole size column to show just the base diameter in Table 1 Part A. Pole height to be determined by designer.
	8	Note 15: Added requirement that a mechanical dampening device must be included on all arms 59' and greater.
4122	1	Changed bracket arm mechanical dampening device to use stranded cable instead of steel rod.
4160	1	Added 42" diameter foundation option for Design 13 poles (lower left).
	2	Added 42" diameter foundation option for Design 13 poles (lower left).
4162	1	Note on lower right side regarding visible marker in the concrete: corrected the PVC conduit dimension to 3/4".
4162	1	Changed the 24" depth of conduit ells entering foundation to be measured from the sidewalk or ground level and also made it a minimum dimension.
4170	1	Deleted dimension between top of pole and span attachment (Varies, 1" min); added 12" dimension between span attachment and bottom of upper handhole.
	New sheet 3 of 7	Added anchor bolt/base plate cover detail and dimensions.
	6 (was 5)	Removed minimum pole height column (height determined by designer); consolidated base moment column and max design base moment column.
4230	1	Eliminated CM-R10-3A pushbutton sign for back of ramp per new ADA policy.
4230	1 and 2	Changed the hand symbol on R10-3A-9(R) so it points the same direction as the arrow per guidance from OMUTCD.