

Slow Streets Columbus – Linden Crosswalk Improvement Locations

Safe Routes to School Locations

- Bancroft St & Genessee Ave – *West and South legs*
- Joyce Ave & Genessee Ave – *East, West, and South legs*
- E 25th Ave & Joyce Ave – *East leg*
- E Hudson St & Joyce Ave – *South leg*
- Dysart Ave & E 23rd Ave – *South and West legs*
- Joyce Ave & Maynard Ave – *upgrade existing sidewalk*
- Hamilton Ave & Duxberry Ave – *North and West legs*
- Dresden St & Blake Ave – *West, East and South legs*
- Dresden St & Duxberry Ave – *East and North legs*
- Ontario St & 22nd Ave – *East leg*
- Ontario St & 21st Ave – *East leg*
- Ontario St & 20th Ave – *East leg*
- Ontario St & 18th Ave – *East leg*
- Grasmere Ave & 26th Ave – *East and South legs*
- Lexington Ave & E 26th Ave – *South leg*
- Reis Ave & Melrose Ave – *East and West legs*
- E Longview Ave & Reis Ave – *West leg*
- E 11th Ave & St Clair St – *South leg*
- Brooks Ave & Chittenden Ave – *South and East legs*
- Cleveland Ave & 17th Ave – *upgrade all four legs*

Total number of crosswalk Improvements: 33